Version **6.00.01.01** :

most important features of version 6.00.01.01 compared to version 5.00.29.00 :
    (Release date : 17.07.2015)

- ADbasic 6 **T12** compiler V6.0.1 , ADwin12.BTL :   (on the CD-Rom for the first time)
    - **support ot the new processor T12** (with 1 GHz , 1GByte, more details : see :
            C:\ADwin\Documents\Hardware\ADwin-PRO\english\ProII-HW_eng.pdf   )
- ADbasic 6 user interface V6.0.0.17 , TiCoBasic user interface V1.5.0.17 : T12 support
- ADbasic / TiCoBasic include / library files :   T12 support
    - ADwinPro2.inc :   bugfix: `P2_SPI_Master_Set_Clk_Wait()`
- ADwin driver (ADwin32/64.DLL, ADTCP32/64.DLL) : higher ENET data transmission rate
- Developer software :   T12 support (double – functions)
    - C - driver V2 :   now also support of multi-threading applications
    - C - driver V1 :   still available for compatibility reasons
- ADlog   V1.3.0 :   T12 support
- ADEthFlash V3.11 :   T12 support
- ADconfig   V3.27 :   bugfix at the input field of „Network Timeout"
                          Subnet Mask is checked more strictly
- ADpro   V5.12 :   rudimental T12 support
- ADwin-Speed-Test V6.0.0.1 : more values for "Number of values to be transferred"
- ADcandb V3.0.6.26779

most important features of version 5.00.29.00 compared to version 5.00.28.09 :
    (Release date : 22.12.2014)

- Kallisté for ADwin V2.6.6.42 :   (on the CD-Rom for the first time)
- ADcandb V2.1.4.18658 :   (now also available on this CD-Rom)
- ADbasic 5 compiler V5.00.29 , TiCoBasic compiler V1.02.24 : diverse bugfixes :
    - occasional problem, if (Far-)East languages are used in Regional Settings of Windows
    - TiCo libraries
- ADbasic 5 user interface V5.2.0.21 , TiCoBasic user interface V1.4.0.21 :
    - now also the column widths of the Project Window are memorized
    - new at TiCoBasic: progress bar at programing of the Bootloader
- ADbasic / TiCoBasic include / library files :
    - EEPROM_Support.inc :   new: ENET3 / S-ATA / USB-support
    - ADwinPro2.inc :   bugfix: `P2_SENT_Set_Serial_Message_Data()`
    - MIO_TiCo.inc, SPI_TiCo.inc : bugfix: `MIO_Get_Digout_Long()`, `Get_Digout_Long()`
- ADwin driver (ADwin32/64.DLL) : ENET interference immunity of `Boot()` function was improved
- Developer software :
    - Matlab - driver V4.08.00 : bugfixes at ADwin_Init (error messages: „winqueryreg" and „wd")
- ADtools TFiFo V5.17 : bugfix: the Units of the columns have not been memorized
- ADtools TString V5.17 : bugfix: Windows font sizes 125 and 150 % have not been supported
- ADlog   V1.2.1 :   internal performance improvements
- ADconfig V3.25 :   improved error message at wrong password
- ADpro   V5.12 :   detection of : *Pro II-DIO-8-D12*
- ADwin-Speed-Test V4.20.0.0 : improved error messages
- last version with official support for Windows 2000, Windows NT
- Linux, MAC OS Version 5.00.10.03b : adwin-lib-5.0.7 :
    - bugfix: adwin-lib driver was not compilable on some Linux versions

most important features of version 5.00.28.09 compared to version 5.00.28.01 :
    (Release date : 02.04.2014)

- TiCoBasic include file :
    - AOut_TiCo.inc : support of the new module :   *Pro II-AOut-8/16-TiCo*
- Developer software :
    - SciLab - driver V1.05.00 : now also support of the 64-bit SciLab version
    - Matlab - driver V4.06.00 : bugfix at Test-License key

- ADconfig   V3.24 :   improved errorhandling
- ADpro   V5.7 :   support of : *Pro II-AOut-8/16(-TiCo) Rev.E10*

most important features of version 5.00.28.01 compared to version 5.00.24.00 :
   (Release date : 27.11.2013)

- ADbasic 5 compiler V5.00.28 , TiCoBasic compiler V1.02.23 : diverse bugfixes
- ADbasic / TiCoBasic include / library files : support of the new modules :
     • *Pro II-AOut-1/16*
     • *Pro II-LS-2*
     • *Pro II-SPI-2-T , Pro II-SPI-2-D*
     • new : `Digout_FIFO_Write_Burst()`
- ADbasic sample programs :
     • standard sample programs now also for Pro II : *ProII_DMO1.bas, ProII_DMO2.bas, etc.*
- ADpro   V5.7 :   support of : *Pro II-AOut-1/16* ; detection of : *Pro II-LS-2*

most important features of version 5.00.24.00 compared to version 5.00.21.01 :
   (Release date : 08.05.2013)

- ADbasic 5 compiler V5.00.24 , TiCoBasic compiler V1.02.20 :
     • diverse bugfixes : powerfunction (only T9, T10)
- ADbasic 5 user interface V5.0.8.21 , TiCoBasic user interface V1.2.8.21 :
     • bugfix: occasional problem on programing the TiCo-Bootloader with big binary-files
- ADbasic / TiCoBasic include / library files : support of the new modules :
     • *Pro II-COMP-16*
     • *Pro II-ARINC-429*
     • *Pro II-MIL-1553*
     • *Pro II-DIO-32-TiCo2*
     • new : `P2_ECAT_Set_Mode()`   (for *Pro II-EtherCAT-SL*)
- ADwin operating system (ADwin11.BTL) :
     • bugfix : problem at Low Prio processes in combination with Ethernet disruptions
- Developer software :
     • dotNET - driver : V1.0.57.0 : :
         ▪ new : examples for WPF (= Windows Presentation Foundation)
         ▪ Online-help reworked
     • Matlab driver V4.05.00 : new : `File2Data()`
- Fieldbus :   ADwin-EtherCAT.xml   (updated for firmware 2.0 of *Pro-II-EtherCAT*)
- ADpro   V5.6.0 :   support of : *Pro II AIn-F8/16 Rev. E04*

most important features of version 5.00.21.01 compared to version 5.00.17.01 :
   (Release date : 17.09.2012)

- ADbasic 5 compiler V5.00.21 , TiCoBasic compiler V1.02.19 :
     • diverse bugfixes (T9, T10) : strings, optimization 2
     • diverse bugfixes (T11) :   `Start_Process()`, `Start_Process_Delayed()`
- ADbasic / TiCoBasic include / library files :
     • ADwinPro2.inc :   support of the new module *Pro II-SENT-4*
     • EEPROM_Support.inc : bugfix : problem, which occured only with some hardware revisions
     • ADwinGoldII.inc , Fieldbus_TiCo.inc : fieldbus errorhandling / errorcodes update
     • MIO-D12_TiCo.inc :   support of the new module *Pro II-MIO-D12*
     • RS_LIN_TiCo.inc :   timing optimized
     • GoldIITiCo.inc :   bugfix : `PWM_Write_Latch()`
- Developer software :
     • Matlab driver V4.02.00 : EXE-files can now be generated with the Matlab compiler
- ADpro   V5.5.0 :   improved errorhandling, if hardware is damaged

most important features of version 5.00.17.01 compared to version 5.00.14.00 :
   (Release date : 28.11.2011)

- ADbasic 5 user interface V5.0.8.19 , TiCoBasic user interface V1.2.8.19 :
  - new at T9 to T11 : "Call Tree"
  - "Managing Projects" enlarged : files of any type can be added to a project, and
    diverse settings can be saved in the project file
  - new : "`<Region>`" (= foldable text range) and „Create Region from Block"
  - new : "documenting self-defined instructions and variables" (i.e.: adding extra information)
  - further diverse improvements and bugfixes
- ADbasic 5 compiler V5.00.17 , TiCoBasic compiler V1.02.17 :
  - bugfix : occasional problem at `MemCpy()` at two-dimensional arrays
  - bugfix: at T11 at Low Prio processes
  - bugfix: at TiCo at big jumps
  - diverse bugfixes among other things at FiFos, libraries (Float-division, TiCo)
- ADbasic / TiCoBasic include / library files :
  - new : `(P2_)Write_Fifo_Full`   (at: Gold II, Gold II TiCo, Pro II)
  - bugfix : `P2_Digin_FIFO_Read_Fast()`
  - bugfix : at T11 at LS-Bus
  - EEPROM_Support.inc : bugfix in timeout handling
- ADwin driver :
  - USB driver now also for 64 bit Windows operating systems
  - ADwin64.Dll : V3.0.464.2 : allows the access for 64-bit applications
- Developer software :
  - dotNET - driver : V1.0.57.0 : completely reworked Online-help
  - Matlab driver V4.01.03 : now identical notes are displayed just once
- ADlog   V1.2.0.0 :   new : now also ADsim-processes can be used
- ADpro   V5.4.5 :   support of : *Pro AIn-F-8/16 Rev. B , Pro II AIn-F8/16 (calibration)*
- ADtest   V5.1.0 :   calibration data can be backed up in files and restored

most important features of version 5.00.14.00 compared to version 5.00.10.00 :
  (Release date : 21.03.2011)

- ADbasic 5 user interface V5.0.6.78 , TiCoBasic user interface V1.2.6.78 :
  - new : "Fontsize" can be set for the source code window
  - further diverse improvements and bugfixes
- ADbasic 5 compiler V5.00.14 , TiCoBasic compiler V1.02.14 :
  - new : `Round()` (returns the nearest integer of a value of data type Float)
  - the start of the timebase for Low Prio processes was moved from the begin of INIT to the end (T9 to T11)
  - bugfix : occasional problem if the passed parameter of a macro is an addition of strings
  - diverse bugfixes among other things at libraries
- ADbasic / TiCoBasic include / library files :
  - new : support for *L16-PWM1* (this add-on has one PWM-output and one SPI-interface)
  - new : support for *Pro II-TC-8 ISO*   (module for thermocouples)
  - new : `P2_Wait_Mux()`   (waits for the end of the multiplexer settling)
  - new : `P2_Digin_Fifo_Read_Fast()`   (Fifo values are written into an array)
  - new : `P2_Burst_CRead_Pos_Unpacked1,-2,-4,-8` (for *Pro II-AIn-F-8/14*)
  - new : EEPROM_Support.inc : (see: C:\ADwin\Tools\Ethernet Interface\Bootloader_eng.pdf)
  - diverse include and library functions : optimization (faster and smaller code)
- Developer software :
  - new : dotNET - driver : V1.0.52.0 BETA especially developed for Visual Studio .Net ; supports 32- and 64-bit
  - Labview driver V3.0 :
    - now 32- as well as 64-bit Labview is supported
    - new: File2Data.vi
  - SciLab driver V1.04.01 :
    - does now work also with new Scilab versions, e.g. 5.1.1 as well as 5.3.0-beta-4
    - optimized errorcode handling
  - Matlab driver V4.01.01 : if necessary , the function ADwin_Init is called automatically
  - ADwinActiveX V 4.0.0.0 : bugfix : occasional problem on Vista, Windows 7
- ADlog   V1.0.48.2 : bugfix at the processes for Gold II (issue at some analog channels)
- ADEthFlash V3.10 :   the required firewall configuration is set automatically
- Fieldbus : new : ESI_ABCC_ECT_V_1_04.XML   (for *Gold-II- EtherCAT*)
- Installation routine : all default- registry- settings are now added also on 64-bit operating systems
- Linux, MAC OS Version 5.00.10.03 :

- improvements, bugfixes : ADbasic compiler, library, generic driver, Scilab driver
- new : Python driver 0.9 ; 64 bit support for ADconfig

most important features of version 5.00.10.00 compared to version 5.00.08.06 :
> (Release date : 10.06.2010)

- ADbasic 5 user interface V5.0.6.68 , TiCoBasic user interface V1.2.6.68 :
  - new : user-defined, external shortcuts can be inserted into the ADtools-bar
  - new : in the context menu of the project window : "Open path in Windows Explorer"
  - new : the results of "Find : All Documents of Project" can be copied into the clipboard
  - "Autocomplete for instruction or variable" was improved
  - "Jump to Declaration" does work now also for user libraries
  - new in TiCobasic : button „R" (= Reset Tico)
- ADbasic 5 compiler V5.00.10 , TiCoBasic compiler V1.02.10 :
  - the DATA-number is now also displayed in the Debug Mode
  - bugfix : occasional problem at programs with codesize > 131072 bytes
  - diverse improvements and bugfixes among other things at libraries (ADbasic), `Min_Long, Max_Long` (TiCo)
- ADbasic / TiCoBasic include / library files :
  - improvements/bugfixes at : CAN, `(P2-)Workload`
  - new : `Wait_Mux, Mod` (integer remainder of a division)
  - new : EtherCAT support for *Gold-II- EtherCAT, Pro-II-EtherCAT, Pro-II-MIO-4-ET1*
- ADbasic / TiCoBasic sample programs :
  - FFT sample programs optimized for T11
  - new sample programs for : *Pro II-AIn-8/18, Pro II-F8/14,16,18, Pro II-PWM-16, Pro II-Cnt, Pro-CO4*
  - new Tico sample programs for Eventsource External
- ADwin driver :
  - new : ADwin64.Dll : V3.0.464.2 BETA : allows the access for 64-bit applications
  - new : ADsim32.Dll : allows access to internal parameters/signals of a compilied Simulink model
- Developer software :
  - new : Pyhton - driver
  - Matlab – driver V4.00.00 : now also Matlab 64-bit is supported
  - Delphi driver : support of Delphi 2009 and 2010
- ADtools V5.17 :   minor bugfixes (colours, large fonts)
- ADtest   V5.0.2 :   completely new developed testprogram for Light-16, Gold and Gold II , calibration for Gold II
- ADlog   V1.0.47.1 :   bugfix in Min/Max function
- Fieldbus : new files :
  - ADwin-EtherCAT.xml   (for *Pro-II-EtherCAT, Pro-II-MIO-4-ET1*)
  - DDF_ABCC_ECT_V_1_03.XML   (for *Gold-II- EtherCAT*)
  - 324-8172-EDS_ABCC_DEV_V_2_3.EDS   (for *Gold-II-DeviceNet*)

most important features of version 5.00.08.06 compared to version 5.00.07.02 :
> (Release date : 28.09.2009)

- Windows 7 : tested and approved for this operating system
- ADbasic 5 compiler V5.00.08 , TiCoBasic compiler V1.02.09 Beta :
  - occasional problem if a `THEN` follows a FIFO
  - occasional generic error at `SEQ_READ8, SEQ_READ16` and `MEDIA_READ`
- ADwin operating system (ADwin11.BTL) :
  - bugfix : occasional problem on stopping of processes with Eventsource External
- ADbasic / TiCoBasic include / library files : support of the new modules :
  - Pro II-RTD-8
  - Pro II-FlexRay-2
  - Pro II-MIO-4
- ADconfig   V3.20 :   the configuration of illegal (UDP) ports is now prevented
- ADtools   V5.15 :   improvements and bugfixes (TButton, TMeter, TGraph, ADtools.exe)
- ADlog   V1.0.46.0 : enhanced ASCII record options
- L16Calib   V2.0 :   bugfix at calibration of Light-16
- Setup.exe   V5.0.0.6 :   faster installation procedure

most important features of version 5.00.07.02 compared to version 5.00.05.10 :
    (Release date : 23.06.2009)

- last version with official support for Windows 98, ME
- ADbasic 5 user interface V5.0.6.27 , TiCoBasic user interface V1.2.6.27 Beta :
    - "Automatic quick info" : automatic display of (declaration-) information if mouse is over a source code element (variable, #Define, (Lib-) Sub, (Lib-) Function)
    - when typing a Sub/Function : information on their passed parameters are shown
    - "Scan Global Variables" button in the Parameter Window : now also global arrays are shown in the Info Window
    - Autocomplete now also at :
        o #INCLUDE together with include filenames, which fit to the selected ADwin- system
        o "Reserved Keywords"
        o many "Codesnippets"
    - now the Process Window also shows, whether the process code contains Debug- / Timing- information
    - printing of a code "selection" is now possible
    - further diverse improvements and bugfixes
- ADbasic 5 compiler V5.00.07 , TiCoBasic compiler V1.02.06 Beta :
    - diverse improvements and bugfixes among other things at Timing Analyser (T9,T10)
- ADbasic / TiCoBasic include / library files :
    - ADwinPro2.inc :   support of the new module : Pro II-AIn-F-8/16
    - several .inc files :   bugfix at : P2_Read_Msg_Con(), Set_TiCo_RingBuffer()
    - FFT.Li* :   bugfix at : FFT(), FFT_INIT() (only if several processes, only T11)
- ADwin driver (ADwin32.DLL) :   now up to 50 TCP/IP Devices can be used (before: 30)
- Developer software :
    - C - driver :   TiCoLoadBin (= sample program for loading TiCo binary files)
    - DASYLab driver :   new help file does work now also on Vista
    - Agilent VEE :   sample programs revised, new : Bas_Dmo6.vee
- ADtools   V5.13 :   diverse improvements and bugfixes
- ADEthFlash V3.8 :   bootloader now also accepts *11c.BTL (= ADsim) files
- ADpro   V5.4.3 : support of : Pro II-AIn-F-8/16
- Profibus :   V2.16 :   updated : Generic Station Description file (for Gold II and PRO II) :   HMSB1811.gsd

most important features of version 5.00.05.10 compared to version 5.00.02.01 :
    (Release date : 12.01.2009)

- ADbasic 5 user interface V5.0.5.10 , TiCoBasic user interface V1.2.5.10 Beta :
    - new : automatic source code formatting (= "Smart format)"
    - new : formatting : "Align comments after source code"
    - new : additional frequency display of the current process
    - further diverse improvements and bugfixes
- ADbasic 5 compiler V5.00.05. , TiCoBasic compiler V1.02.03. Beta :
    - better syntax checking at the preprocessor
    - diverse improvements and bugfixes among other things at libraries and in Debug Mode
- ADbasic / TiCoBasic include / library files :
    - ADwinPro2.inc, DIO32TiCo.inc :   edge output FIFO for DIO-32-TiCo Rev E03
    - ADwinGoldII.inc, GoldIITiCo.inc : new: Digin(); new option: Gold II-Storage-16 (16 GB flash memory)
    - ADwinGoldII.inc :   new: SEQ_READ8(), SEQ_READ16(); bugfix: Profibus
    - String.Li* :   bugfix at function LNGTOSTR : inaccuracies at very big values
- ADwin driver (ADwin32.DLL) :   bugfix at Enet at GetData() (only if network timeout)
- Developer software :
    - ADwinActiveX   V 3.0.0.3 :
        o improved error handling at diverse functions
        o bugfix : memory problem at GetData_String() and at Get_FPar_Block_Double()
- ADconfig V3.18 :   bugfix : occasional problem at "Scan AEI"
                            now also 00-22-71-XX-XX-XX is selectable as default MAC addresse range
- ADtools   V5.10 :   TButton : new option : "Close all ADtools"
                            TButton : new option : transfer data from a file to a DATA
                            TParFPar : bugfix : at importing of comments
- ADpro   V5.4.2 :   minor changes
- ADlog   V1.0.45.3 :
    - new processes for Pro II-AIN-32/18 (16 and 32 channels)

- • new: "Moving X-Axis" (= softscrolling of the X-Axis at slow sample rates)
  - • bugfix at drawing of several windows, bugfix at configuration with several windows
  - • diverse improvements
- Profibus : new Generic Station Description file (for Gold II and PRO II) : HMSB1811.gsd

most important features of version 5.00.02.01 compared to version 5.00.00.01 :
   (Release date : 17.06.2008)

- ADbasic 5 user interface V5.0.2.0 :
  - • improved operator guidance at the useage of libraries
  - • bugfix at : Parameter Scan, 64-bit Windows operating systems
- TiCoBasic V1.2.2 Beta :   diverse improvements and bugfixes
- ADbasic / TiCoBasic include files :
  - • ADwinGoldII.inc :   Profibus support and diverse improvements
  - • GoldIITiCo.inc :   Gold II supports now also TiCo
  - • ADwinPro1.inc, ADwPDIO.inc :   bugfix at `DIGOUT`
  - • ADwinPro2.inc :   - the new module Pro II-PROFI-SL is now supported
                            - bugfix at `P2_BURST_INIT`
  - • AInTiCo.inc :   the following new modules are now supported :
                            - Pro II AIN 32/18-D-TiCo
                            - Pro II AIN 8/18-L2-TiCo
- ADPro   V5.4.1 :
  - • the TiCo on a module is stopped, and again started on closing of the window
  - • support of : PRO II-CNT-D/-T/-I and all Pro I and Pro II-CAN-modules
  - • diverse improvements and bugfixes : problem fixed at 64-bit Windows operating systems
- ADlog   V1.0.44.0 :
  - • diverse improvements in the user interface and diverse bugfixes
  - • moving average filter : "Values count" now up to 10000
- Setup.exe (V 5.0.0.2) :
  - • bugfix : compiler was not found, if ADwin-software was not installed to C:\ADwin
  - • faster startup of the ADbasic 5 user interface caused by the useage of NGEN
- JAVA   V1.2.2 :
  - • multiple threads can now access the same ADwinDevice-Object („Thread safety")

most important features of version 5.00.00.01 compared to version 4.20.10.05 :
   (Release date : 02.04.2008)

- TiCoBasic V1.2.1 Beta :   diverse improvements and bugfixes
- ADbasic 5 V5.0.0.0 :
  - • totally new user interface (see chapter "News in ADbasic 5" in the ADbasic help)
  - • bugfix at : `MEMCPY` , calculations with the constant 0 , libraries
  - • .NET-Framework 2.0 is now required
- ADbasic include files :
  - • ADwinGoldII.inc :   Gold II is supported
  - • ADwinPRO2.inc :   the following new modules are now supported :
                            - PRO II-CAN-2 , PRO II-CAN-2-LS
                            -.PRO II-LIN-2
                            - PRO II-RSx-2 , PRO II-RSx-4
                            - PRO II-PWM 16 , PRO II-PWM-16-I
                            - PRO II-CNT-D, PRO II-CNT-T, PRO II-CNT-I
                            - PRO II-TRA-16
- ADwin driver (ADwin32.DLL) :   bugfix at T11 at `GetData()` (only if count > 22.000.000)
- Developer software :
  - • Matlab driver :   now Matlab version 7.6 (R2008a) is supported ; `Processor_Type` now also for T10, T11
- ADconfig   V3.16 :   bugfix : visible / invisible window at „Configure AEI"
- ADPro   V5.4.0 :
  - • support of : PRO II-DIO-32, PRO II-TRA-16, PRO II-OPT-16, PRO II-RSx-2, PRO II-RSx-4
  - • .NET-Framework 2.0 is now required
- Pro-Storage V1.13 :   bugfixes ; the firmware version number is now displayed
- ADlog   V1.0.42.0 :
  - • Gold II is supported

- • setting of the Samplerate was improved
- Fieldbus / Profibus : new file : 321-2932-HMS_1811.gsd
- Setup.exe (V 5.0.0.1) :
    - • automatic deinstallation of an already installed ADwin-software
    - • check if the Microsoft (R) .NET Framework 2.0 is installed
- One-Click-Install.bat (V1.0 Beta) : alternative installation of the ADwin Software via command line

most important features of version 4.20.10.05 compared to version 4.20.10.00 :
   (Release date : 27.07.2007)

- TiCoBasic V1.1.02 Beta : diverse bugfixes ; new : `RINGBUFFER`
- ADtools V5.7 : new : TGraphTiCo
- ADbasic include files :
    - • ADwinL16.inc : bugfix : `SEQ_INIT()` ; new (for CAN) : `READ_MSG_CON()`
    - • ADwinPRO1.inc, ADwPEXT.inc, ADwGCAN.inc : new (for CAN) : `READ_MSG_CON()`
    - • ADwinPRO2.inc : Pro II-DIO-32 Rev. E is now supported
- Developer software :
    - • Matlab driver : now also Matlab version 7.4 (R2007a) is supported ;
                       "Standalone Applications" (EXE) can be created
    - • DASYLab driver : new : support of DASYLab (version 7 , 8 and 9)
    - • Testpoint driver : Realtime Object 1.4.2 : new action : Fifo Full
- ADlog V1.0.41.0 :
    - • measurement processes for Pro, Pro II, Gold and Light-16 were optimized ; `L16_MODE` for Light-16 Rev.B

most important features of version 4.20.10.00 compared to version 4.20.08.02 :
   (Release date : 20.03.2007)

- TiCobasic V1.1.01 : Real-Time development tool for TiCo processors
              (The TiCo-processor is a standalone, free programmable add-on processor,
              which is currently used in certain *ADwin-Pro II*-modules)
- ADbasic V4.20.10 :
    - • Windows Vista is supported (new HTML Help system)
    - • bugfix at : `CASEELSE`
- ADwin operating system (ADwin11.BTL) :
    - • bugfix: occasional problem caused by PC communication
    - • bugfix: occasional problem on starting several processes
- ADbasic include files :
    - • ADwPDIO.inc, ADwinPRO1.inc : bugfix at `PWM_ENABLE`
    - • ADwPEXT.inc, ADwinPRO1.inc : bugfix at Profibus, Interbus
- Developer software :
    - • Delphi driver : bugfix at Process_Status()
- ADconfig V3.13 : support of Windows Vista
- ADtools V5.7 : :
    - • Windows Vista is supported (new HTML Help system)
    - • bugfix at TButton, TGraph, TLed
- ADEthFlash V3.7 : support of Windows Vista
- ADPro V5.3.2 :
    - • SSI-Interface of CO4-D modules is supported
    - • the four counters of CO4 modules are supported
    - • backup and restore of calibriation data (modules AIn-F8/18, AIn-F8/14, AIn-8/18 and AIn-32/18)
- ADlog V1.0.40.2 :
    - • Windows Vista is supported (new HTML Help system)
    - • bugfix : occasional problem on recording in Diadem-format
- Setup.exe V4.7 : installs current versions of the "Adobe Reader"
- Linux, MAC OS : SciLab is now supported

most important features of version 4.20.08.02 compared to version 4.20.05.07 :
   (Release date : 16.11.2006)

- ADbasic V4.20.08 :
    - bugfixes at : libraries, `STRINGS`, `SHIFT_LEFT` , `SELECTCASE` und `MEMCPY`
    - bugfix at access to Pro-II bus
    - bugfix at programcode located in `DRAM_EXTERN` (only T11)
    - bugfix (at T9 and T10) on calculation of constants (1 / const.)
- ADwin operating system (ADwin11.BTL) :
    - bugfix: occasional damage of low prioritized processes caused by PC communication
- ADwin operating system (ADwin10.BTL) :
    - bugfix at the PC communication functions Fifo_Full, Fifo_Empty, Fifo_Clear
    - bugfix at code in `LOWINIT` at externally controlled processes
    - bugfix at : `TAN`
- ADbasic include files :
    - ADwinPRO1.inc :   LS-Bus support (T11)
    - ADwPEXT.inc :   LS-Bus support (T9 und T10)
    - ADwL16.inc :   LS-Bus bugfix and optimized
- Developer software :
    - Labview driver V2.2 :
        - changes because compatibility to Windows / Linux / Mac OS
- ADconfig   V3.9 :
    - Web Interface can be started from the Scan- window
    - „Ping" can be executed
    - bugfix : it was possible to create a duplicate Device No   (at Edit : USB/Link)
- ADPro   V5.2.2510 :
    - LS-Bus- module is supported
    - calibriation of the modules AIn-F8/18, AIn-8/18 and AIn-32/18
    - diverse improvements and bugfixes
- ADlog   V1.0.37.1 :
    - number of points per line increased from 10000 to 20000
    - higher performance at lower CPU-load
- Linux, MAC OS :
    - ADbasic- compiler V4.20.07.00 (only for Linux)
    - Linux / Mac-library (= shared library) V3.0.449 :
        - support of Mac OS X 10.4 for ADwin-systems with Ethernet-interface
    - Labview driver V2.2 (Linux and MAC)
    - numerous functional improvements

most important features of version 4.20.05.07 compared to version 4.20.04.04 :
     (Release date : 06.09.2006)

- ADbasic V4.20.05 :
    - bugfixes at : `MEMCPY, SELECTCASE` (only at `CASE 0`)
    - bugfix on opening of ADbasic project files (*.ABP)
    - bugfix at instructions for the modules Pro-II-AOut- 8/16 and Pro-II-AIn-F-8/14
    - occasional problem with access to Pro-II bus
- ADbasic include files :
    - ADwinPRO2.inc :   bugfix at the modules AIn-8/18 and AIn-32/18
                         (concerns the instructions : `P2_SEQ_INIT` and `P2_BURST_READ_INDEX`)
    - ADwinPRO1.inc :   new : `TC_READ_B`
    - ADwPEXT.inc :   new : `TC_READ_B`
    - ADwPAD.inc :   bugfix for T10 at : `READ_ADCF8, READ_ADCF8_PACKED`
    - ADwL16.inc :   new :   support of the module HSM-24V (via LS-Bus)
- Developer software :
    - examples for Excel driver (ActiveX and Visual Basic)
    - SciLab V1.03.00 :   (on the CD-Rom for the first time)
    - Matlab :   warning "… case-sensitive match for 'adlab' … " fixed
- ADPro   V5.2.2406 : diverse improvements
- ADlog   V1.0.36 :
      - new : processes and configurations for Pro-II modules
      - diverse improvements

most important features of version 4.20.04.04 compared to version 4.20.03.07 :

(Release date : 17.05.2006)

- ADbasic V4.20.04 :
    - bugfixes at : libraries, strings, `MEMCPY`, `SHIFT_RIGHT`, `SHIFT_LEFT`
    - bugfix at programcode located in `DRAM_EXTERN` (only T11)
    - bugfix at optimization level 2 (only T9 and T10)
    - bugfix at powerfunction (only at ^2 or ^3)
- ADwin11.BTL :
    - bugfix at SetData at certain values of Startindex and Count
    - bugfix at GetFifo (only at high prioritized processes with long lasting `EVENT` section)
- ADbasic include files :
    - ADwinPRO2.inc :   new : support of the modules AIn-8/18, AIn-32/18 and AOut-8/16 (Rev. E)
                                       (new instructions : `P2_ADC…` , `P2_SEQ…` , `P2_DAC…` , `P2_DAC4_PACKED`, ...)
    - ADwinPRO1.inc as well as ADwPEXT.inc : new instr. : `TCJ_DIG_TO_TEMP`, `TCK_DIG_TO_TEMP`,
                                                    `PT100_DIG_TO_TEMP`, `PT100_DIG_TO_R`
- ADwin driver (ADwin32.DLL) :   bugfix at Get_Digout() and Set_Digout()
- ADtools : V5.5 : :
    - TGraph : new : FFT
    - now each tool can be moved by ADtools.exe and brought "on top" of the screen
    - new : ADstartpanel.exe
    - diverse bugfixes and improvements
- ADEthFlash V3.4 :   new : button for Bootloader dis-/enable (from ENET firmware 2.66 on)
- ADlog   V1.0.33 :
    - Start/Stop Communication Buttons are now located in the toolbar of the main window
    - math. functions improved
    - diverse improvements

most important features of version 4.20.03.07 compared to version 4.20.03.00 :
   (Release date : 30.03.2006)

- ADbasic include files :
    - ADwinPRO2.inc :   new : support of the module Pro-Ain-F-8/14 (Rev. E)
                                     bugfix at `CPU_EVENT_CONFIG()`
    - ADwL16.inc : new instructions for Rev. B : `SEQ_READ()`, `SEQ_INIT()`, `L16_MODE()`
                            only DIO_02 :   `SSI_…()`
                            only DIO_02 or DIO_03 : `DIGIN_LONG_E()`, `DIGOUT_LONG_E()`
- ADwinTCPIPserver V1.7.0 :   optimisation of data throughput
- Pro-Storage : Pro-Storage_MP.BAS :   bugfix at writing into a file
- L16Calib.exe V2.0:   now also suitable for calibration of the new L16 Rev. B
- ADconfig   V3.5 :   bugfixes at DHCP
- ADlog   V1.0.32 :
    - new : math. functions : Addtion, Substraction
    - new : two configurations with 16 channels for ADwin Gold
    - improved Zoom at several Y-axis
    - Recording mode : enhanced triggermodes
    - Recording mode : now also header line (with the names of the channels)

most important features of version 4.20.03.00 compared to version 4.20.01.08 :

- ADbasic V4.20.01 , ADwin11.BTL :
    - Conditional compilation with `ADWIN_SYTEM` (= `ADWIN_GOLD`, `ADWIN_L16`, `ADWIN_PRO`)
    - names of variables and `#DEFINE` may not contain special characters (+-*/^.;&|%$§#) any longer
    - bugfix at libraries at T11
    - bugfix at programcode located in `DRAM_EXTERN` (only T11)
    - bugfix at concatenation of strings
    - bugfix at setting of the Low Priority Level
    - bugfix at `#DEFINE`, which is used in a `SUB` or a `FUNCTION`
- ADbasic include files :
    - ADwpAD.inc :   new : `READ_ADCF4/8`, `READ_ADCF4/8_PACKED`
    - ADwinPRO2.inc :   new : support of the module Pro-Ain-F-8/18

- ADbasic libraries :
  - String.Li* : bugfix at function VALF : Exponent was ignored, if it contained a "+" character
- ADtools : TProcess V5.3   supports the new Debug- Mode messages of the Pro-II-Bus
- ADPro   V5.1.2153 : diverse improvements
- ADlog   V1.0.27 :   diverse improvements

most important features of version 4.20.01.08 compared to version 4.01.19.00 :

- ADbasic version 4.20.01 , ADwin11.BTL :
  - **support of the new processor T11** (with 300 MHz , more details : see document :
        C:\ADwin\Documents\Hardware\ADwin-PRO\english\Pro_T11_eng.pdf   )
  - new instructions (only T11) : - START_PROCESS_DELAYED, RESTART_PROCESS, MEMCPY, CPU_SLEEP, P1_SLEEP, P2_SLEEP
  - maximum codesize (per process) is 1.000.000 Byte when using T11 processor
  - bugfix at Shift_Left
  - bugfix at string assignment and string addition (only when using a T10 processor)
  - Parameter Scan did not work for Par_80, FPar_80
  - now a warning is generated, if the operator " - " is directly following after the operators " / " or " ^ ".
- ADbasic include files :
  - ADwinPRO1.inc :   new file for processor T11 (for well-known bus Pro I)
  - ADwinPRO2.inc :   new file for processor T11 (for new Bus Pro II)
     new instructions : CPU_EVENT_CONFIG, CPU_DIGIN, CPU_DIG_IO_CONFIG, CPU_DIGOUT
  - ADwinPRO_ALL.inc : new universal include file for all processors T4 to T11
- ADbasic libraries :
  - String.Li* : bugfix at functions LNGTOSTR and FLOTOSTR
  - FFT.Li* :   optimized version for T11, bugfix at function FFT_Phase()
- ADbasic sample programs :
  - new sample programs : Pro-AIn8-14_Seq.BAS, Pro-AIn8-14.BAS
- ADwin driver bugfixes :
  - occasional problem with SetData function (ENET)
  - occasional loss of PC physical memory on useage of function SetFifo (ENET)
- Developer software :
  - Agilent VEE :   sample programs revised, new : Bas_Dmo7.vee
  - Matlab :   ADlab.dll is now located in the directory "C:\ADwin\Developer\Matlab\ADwin"
- ADPro version 5.0.2077 :
  - support of processor T11 ; improved user interface
  - hint : ADpro_Old has to be used for processors T4 to T8
- ADlog   V1.0.24 :   diverse improvements ; reworked Online-help
- ADEthFlash V3.3 :   new : button for Bootloader dis-/enable (from ENET firmware 2.66 on)
- Setup.exe (version 4.3.0.0) :
  - there is no more check, whether the user is a so-called "Administrator", but only, whether the user is a member of the Administrators' group
  - check if Microsoft (R) .NET Framework 1.1 is installed
- JAVA   V1.2 :
  - support of processor T11
  - new methods : Set_Processdelay, Get_Processdelay
  - the max. data transmission rate at GetData was increased (from ENET firmware 2.66 on)

most important features of version 4.01.19.00 compared to version 4.01.17.01 :

- ADbasic version 4.01.19 :
  - bugfix at : "Compiler Options" -> "System" -> "ADwin-GOLD"
- ADlog   V1.0.21 : diverse improvements ; reworked Online-help

most important features of version 4.01.17.01 compared to version 4.01.15.00 :

- ADbasic version 4.01.17 :
  - display of line and column number in the "Status Bar"
  - new ADbasic systemvariable PROCESSDELAY (identical with GLOBALDELAY)

- bugfixes at #defines, #endif and optimization level 2
- bugfix at : SIN, COS, EXP, LOG, LN, SQRT, TAN, ARCSIN, ARCCOS, ARCTAN
- bugfix at : variable ^ constant ^ constant
- bugfix : Mark Controlblock did not work under Win XP
- ADbasic include files :
  - ADwpext.inc : support of the new thermocouple- module TC-8 ISO
- ADbasic library files :
  - Sting.Li9 / .LiA : bugfix at STRMID, STRLEFT, STRRIGHT, FLOTOSTR
- ADwin driver (ADwin32.DLL) :
  - max. data transmission rate at GetData was increased from 4.8 to 6 Mbyte/s (from ENET firmware 2.66 on)
  - bugfix : write permissions are no longer needed in the root- directory on the fixed disk (C:\ )
  - bugfix : now also dots (= periods) are allowed in the path of the ADwin?.BTL
- Developer software :
  - ADwinActiveX   V 3.0.0.1 :
    - o improved error handling now supports also Multi-Threading
    - o bugfix at Set_Language()
  - Labview driver :
    - o improved error handling now supports also Labviews Multi-Threading
    - o the DLL-calls were made independent from the user-interface; therefore the user-interface is operable even during long-lasting DLL-calls (e.g. if ADwin-system is not accessible)
    - o calling convention of the VI's is no longer "as caller" but "standard" , therefore possibly higher speed
    - o from now on the current driver does only support Labview versions >= 6.0
    - o bugfix : at GetData_String
  - Matlab driver :
    - o new : Get_Last_Error_Text, String_Length, Get/SetData_String, Get_DeviceNo, Show_Errors
    - o Online-help : 'help ADwin' can now be called in the 'Command Window'
  - Testpoint driver : Realtime Object 1.4.1 :
    - o new action : Read Fifo Int32 : necessary for integer numbers greater than 16777215 (= 24-bit)
    - o Read Parameter All and Read Parameter Block are now returning signed values
- ADconfig V3.0 :
  - o completely new designed and clearly arranged user interface
  - o scanning of ADwin-systems (Scan_AEI) is now integrated into ADconfig
  - o context- sensitive Online- help
- ADEthFlash V3.2 as well as ADtools V5.1 :   adaptions for future processors
- ADlog   V1.0.19 :   diverse improvements
- JAVA   V1.1 :   bugfixes

most important features of version 4.01.15.00 compared to version 4.01.13.00 :

- ADbasic version 4.01.15 :
  - new samples :   RS232_send_string.BAS, RS232_receive_string.BAS
- ADwin operating system :
  - ADwin10.BTL :   bugfix at ADBasic instruction START_PROCESS()
  - ADwin9.BTM :   issue with Link- Bootloader fixed
- Developer Software :
  - Delphi driver :   bugfix : wrong return values at function ADBoot() (at processors T2, T4, T5, T8) as well as function Processor_Type() (at T5 and T9)
  - Matlab driver :   bugfix: function 'Get_Globaldelay' : value was taken from processnumber+1
  - C - driver :   sample programs revised
  - Testpoint driver : systemobject 1.3.8 : new option „Load Standardprocesses" (i.e. loading of ADwins9.btl is possible)
  - ADwinActiveX   V 2.0.0.11 :
    - **New :** sample programs for VB.NET and C#.Net
    - Intouch sample programs adapted to Intouch 9.0
  - **New :** GUI_development.pdf :   advice for developers on the drivers and samples of the different development environments
- ADwinTCPIPserver V1.6.3 :
  - Bugfix : big data throughput caused a timeout at 'SetData'
  - now several PCs can access an ADwin-system via the ADwinTCPIPserver
  - Help- file completely revised
- ADEthFlash V3.0 :   Online info about EEprom Support now also for ADwin Ethernet interface 2
- ADtools   V5.0 :   at all ADtools :   buxfix at the DeviceNo (only if last used DeviceNo does not exist any more)
  - TPoti: the Focus-color and the NonFocus-color is now selectable
  - ADtools.exe : the recent used path is remembered on saving and opening *.def files

- ADlog   V1.0.11 :   datalogging software for ADwin systems
  - ADbasic measurement processes reworked
  - higher performance of the graphic display
  - X-axis can be shown in a date / time formatted manner
  - diverse bugfixes and improvements
  - Help- file now also in English

- **Linux** : completely reworked : ADbasic- compiler V4.01.11 and driver V3.0.446 (now also ENET support)

most important features of version 4.01.13.00 compared to version 4.01.10.02 :

- ADbasic version 4.01.13 :
  - bugfix : at `SHIFT_LEFT`, `SHIFT_RIGHT`, `ABS`, `SIN`, `COS`, `EXP`, `LOG`, `LN`, `SQRT`, `TAN` if one of these functions uses itself as a function parameter
  - bugfix : accuracy of calculations at division by a constant
  - bugfix : printing in „landscape"- orientation
  - bugfix : at optimization level 2 on calculation with constant expressions
  - new Compiler Option :   Remember Device No.
- ADbasic Include files :
  - ADwpdio.inc : new subroutine : `RTC_GET()`
  - ADwpAD.inc : bugfix : `BURST_CREAD ()`
  - ADwpext.inc : bugfixes : `RS_RESET()`, `WRITE_FIFO()`, `GET_LINE_STATUS()`
  - ADwGCAN.inc : new file for CAN-expansion at ADwin-GOLD
  - PRO-STORAGE_SP.inc : bugfix : `MEDIA_RD_…`
- ADwin driver bugfixes :
  - occasional problem with SetData function on ENET – fixed only together with firmware >= 2.53 and 2.64 respectively
  - occasional problem with GetFifo function (ENET)
- Developer Software :   Testpoint driver :
  - Realtime Object 1.3.8 : bugfix : Read Parameter returned only unsigned values.
  - A/D Object 1.3.5 :   bugfix : at Sample A/D Action (all 16-bit values < 32768 were miscalculated)
- ADEthFlash V2.9 :   EEprom Support now also for ADwin Ethernet interface 2
- ADtools   V4.9 :   diverse buxfixes at TGraph, TDigit, TPoti, TPar_Fpar
  - TGraph :   new : now up to 16 analog channels and 32 digital channels
  - TGraph :   new : importing of data from a textfile
  - TGraph :   new : timer can be disabled by pressing the SHIFT- key during startup
  - TGraph :   new : values can be edited by double-clicking in the Textwindow
  - TProcess :   new : ADbasic Debug Errors are displayed
  - TProcess :   new : PM, DM, DX and Codesize are displayed
  - TProcess :   new : Globaldelay can be set also in frequency units (Hz, kHz, MHz)
  - TPar_Fpar : new : comments can be imported from ADbasic #defines.
- ADlog   V1.0 :   datalogging software for ADwin systems**.   (on the CD-Rom for the first time)**

- **JAVA** V1.0 : JAVA- interface for ADwin-systems with Ethernet interface **(on the CD-Rom for the first time)**

most important features of version 4.01.10.02 compared to version 4.01.01.21 :

- ADbasic version 4.01.10 :
  - bugfix : if the same Fifo is used several times within an expression
  - diverse bugfixes at optimization level 2 (e. g. at : `Digin()`)
  - bugfix : at integer expression VARIABLE * CONST / CONST or VARIABLE / CONST * CONST
  - now more than 128 characters are allowed for file-/pathname
  - bugfix : occasional problem with libraries
  - bugfix : on task-switch among several low prioritized processes
  - improved checking of the function parameters at : `Fifo_Full()`, `Fifo_Empty()`, `Fifo_Clear()`
  - improved checking of the file, which is passed to the `IMPORT` instruction
- ADwin operating system (ADwin9.BTL, ADwinS9.BTL , ADwin10.BTL) :
  - bugfixes at the communication process and at the process-scheduling of low priority processes
- Developer Software :
  - Matlab driver :   new function Data_Length()
  - C - driver :   sample programs revised

- • ADwinActiveX   V 2.0.0.10 : bugfix at function "Boot": If property Exception_Enable is used, then no exception was initiated.
- Pro-Storage V1.8 :   bugfixes ; now also FLOAT can be stored/loaded

most important features of version 4.01.01.21 compared to version 4.01.0106 :

- ADbasic library files : new : FFT library now also for T10 (FFT.Lia)
- ADbasic include files :
  - • ADwpdio.inc : new : instructions for the COMP16 module ; bugfix on Pro-Storage (RTC)
  - • ADwpext.inc :   corrected : SET_RS()
  - • ADwpda.inc :   new instructions for memory option (for example Pro-Aout-4/16-M2)
- ADwin driver bugfixes and optimizations :
  - • occasional problem with SetData function on ENET
  - • occasional problem with access from several PCs to one ADwin-system (ENET)
  - • better usage of the transmission bandwith on simultaneous access from one PC to several ADwin-systems with the same TCP/IP port.
  - • ENET optimizations at SetFifo function , especially active with Win9X/ME PCs
- ADwin operating system (ADwin9.BTL, ADwinS9.BTL , ADwin10.BTL) :
  - • Bugfix : on starting a second process
- Developer Software :
  - • VisualBasic driver : return value of the function Get_Globaldelay
  - • Testpoint driver :   A/D Objekt now also for GOLD and L16
  - • Labview driver :   Acquire.vi now also for GOLD and L16
  - • InTouch driver :   sample programs are on the CD for the first time
  - • Matlab driver :   some functions returned a duplicate result
- GoldCalib   V1.0   this is the calibration program for ADwin-Gold-ENET/USB
- Pro-Storage V1.6 :   now also module addresses > 99
- ADEthFlash V2.2 :   supports now also firmware 2.52

most important features of version 4.01.0106 compared to version 4.00.0600 :

- ADbasic version 4.01.01 :
  - • Mark Controlblock now also for SELECTCASE
  - • new functions : CAST_FLOATTOLONG(), CAST_LONGTOFLOAT()
  - • bugfixes :
    - at optimization level 2
    - constant –2147483648 was not accepted
    - problem with Fifo (Float) as LValue
    - Open All Includes did not work in certain cases
    - Debugmode did not work in LowInit section
    - problem on handling with strings
    - on ADC instruction if the first function parameter is not a constant
    - error on nested libraries with T10 if array is in external memory (DX)
- ADbasic include files :
  - • ADwinpro.inc : new function : CPU_DIGIN()
  - • ADwpdio.inc : new: Pro-Storage : PCMCIA- memory and real-time clock
- Developer Software :
  - • Testpoint driver : support of the T10 processor
  - • Labview driver : paths adapted for Labview 7 and sample programs
  - • C - driver : reworked
- ADEthFlash V2.1 :   support of ADwin Ethernet interface 2

most important features of version 4.00.0600 compared to version 4.00.0500 :

- ADbasic version 4.00.06 :
  - • bugfix : old incompatible libraries are now rejected
  - • FFT– library newly generated with ADbasic 4
- ADconfig V2.7 :
  - • bugfix (problem, if all Device_No have been deleted)
- ADPro Version 4.1 :
  - • support of the new Pro-AIN 8/14, Pro-AIN-32/14, Pro-AIn-8/16 Rev C, Pro-AIn-32/16 Rev C

most important features of version 4.00.0500 compared to version 3.20.1200 :

- ADbasic version 4.00.05 :
    - T10 Processor (80 MHz) is now supported (*1)
    - Projectmanagement : A projectfile can be created, which is able to open several ADbasic files (*1)
    - new optimisations for T10 : up to 10 % less program memory (PM) needed, compared with the T9
    - support also of the ADwin-Gold-ENET and ADwin-Gold-USB (both Rev. B1 or greater)
    - for ADwin-Gold : multiplexer settling time changed from 1,5 to 2,5 µs for the**ADC12** instruction. Programs with the ADC12 instruction now need more CPU- time and eventually have to be reworked.
    - Load Standardprocesses : If "No" => approx. 11 kByte bigger free program memory (PM)
    - Default Settings for Directory (BTL, INC, LIB) now also for several Users under NT, W2K, XP
    - commandline functionality
    - improved user interface :
        - all 80 PARs/FPARs in Parameter window
        - simultaneous control over all 10 processes in the "Processes Window" (*1)
        - new button: "Enable cyclic update"
        - new button: "Parameter Scan" (*1)
        - system (Gold, Pro, Light-16, ..) is now selectable. (= replacement for: "16 bit resolution")
        - shortcuts für Boot, Compile, Start, Stop, Parameter Scan, (Un-)Comment Block, In-/Outdent
        - permanent display of the options :
            - Process X delay   (= former called : (Global-) Delay)
            - Initial Processdelay   (= former called : (Global-) Delay)
            - Device No. , Eventsource , Priority , Process number , Optimize Level
    - new instructions :
        - Sleep()
        - AT DM_LOCAL, AT DRAM_EXTERN can optionally be specified on BYREF parameters of libraries (for the reason of code optimisation
        - #IF PROZESSOR = T10 THEN
    - bugfixes :
        - #DEFINE now also allowed on strings
        - at powerfunction (^) , at optimisation level 2, at IMPORT instruction
    - revised editions of ADbasic Manual and Tutorial
    - revised edition of context- sensitive ADbasic Online Help

    - *1 = a new ADbasic4 license is necessary for this feature

- ADbasic include files :
    - Adapted for processor T10 :   ADwpAD.inc, ADwpDA.inc, ADwpDIO.inc, ADwinPro.inc, ADwpEXT.inc
    - ADwpAD.inc : new for Pro-AIN-F-X/14 (Rev B2) : BURST_CSTART(),BURST_CREAD(),SYNC_MODE() new instructions for sequence control : SEQ_…() support of new Pro- AIN 8/14 , Pro- AIN 32/14
    - ADwGcnt.inc : new for ADwin-Gold-ENET/-USB (Rev. B1 or greater) with CO1 Option : CNT_GETSTATUS() , CNT_RESETSTATUS() , CNT_SE_DIFF()
- ADbasic Library files : new : ADwpEXT_lib.Li9, ADwpEXT_lib.LiA
- ADwin driver bugfixes :
    - occasional problem (errorcode 2000) with SetFifo function on ENET
    - occasional problem with path-/filename with function ADwin_Debug_Mode_On
- ADwin operating system (ADwin9.BTL, ADwinS9.BTL) :
    - ADwinS9.BTL : approx. 11 kByte bigger free program memory (PM)
- Developer Software :
    - Labview driver :   improvements on Stopdac, Startdac, Acquire, Process_Status
    - Delphi Treiber :   improvements on Get_last_error_text
- ADtools V4.6 : TProcess : Processor T10 is now supported ; bugfixes at TPoti and TPar_FPar ; improvements at TGraph
- ADEthFlash V2.0 :   Processor T10 is now supported
- ADPro Version 4.0 :   Processor T10 is now supported
- ADtest V1.7 : (settings are now stored in the registry in location „HKEY_CURRENT_USER")
- ADwinTCPIPserver V1.2 : on errors, now errorcodes are displayed
- ADbootload V3.4 :   bugfix

most important features of this version compared to version 3.20.0804 :

- ADbasic version 3.20.12 :
    - Bugfixes on libraries and `Sleep` instruction in optimization level 2
    - Bugfix on sin-, cos- and powerfunction (^) at processes with low priority
- ADwin driver :
    - improved USB driver
- ADwin operating system (ADwin9.BTL) :
    - Bugfix on Booting the ADwin-Pro system (undefined behaviour)
- Developer Software :
    - Matlab driver : (license key for this is required).
- ADtest V1.6 : (settings are now stored in the registry in location „HKEY_CURRENT_USER")
- ADwinTCPIPserver V1.1 : (for the first time on the ADwin-CD)

most important features of this version compared to version 3.20.0703 :

- ADbasic version 3.20.08 :
    - Bugfixes on libraries and on calculations with signed constants
    - The default setting for "16 Bit resolution" is now "Yes"
- ADbasic include files improved :   ADwL16.inc , ADwgcnt.inc , ADwpad.inc
                                                      ADwpDIO.inc   (new: instructions for Pro-CO4 , Pro-DIO-32 (Rev B))
- ADbasic example "Bas_Dmo7.bas" improved
- FFT– library available for the first time in : C:\ADwin\ADbasic3\lib
- ADwin driver improvements :
    - On using the functions GetData_Float / GetFifo_Float / GetFPar_All , possibly existing invalid bit patterns (e.g. because of not initialized data) are now set to Q-NAN
- Developer Software :
    - improvements in Labview and C – driver
    - **ADwinActiveX V 2.0** available for the first time in : C:\ADwin\Developer\ActiveX
      Therefore for the first time a driver for the developer environment :
        - **Visual Studio .NET**: C#, VC++ 7, VB.NET
      As well as for the developer environments :
        - Visual C++ 6, Visual Basic 6 , Borland Delphi , Borland C-Builder , Agilent VEE, etc.
- ADPro Version 2.9 : The revision identifier is now displayed for all (i.e. also old) modules
- Windows Installer Engine version 2.0 :
    - The new engine version will be installed automatically, if necessary.
    - Problem on deinstalling older versions (Error 1316) is now fixed
    - Service pack 6 is now required for WinNT (SP6 is available on CD in directory : NT4_SP6a).

most important features of this version compared to version 3.20.0109 :

- ADbasic version 3.20.07 :
    - Bugfixes on strings, libraries, ADC12, optimization level 2, power function (^)
    - Escape sequences for strings
    - Constants are now combined/calculated at compile-time, no longer at runtime. This is valid for all optimization-levels. Advantage : programs are executed faster. But **ATTENTION** : waiting times (e. g. for multiplexer settling time) , which have been implemented by program code containing calculations with constants, are now shorter. They have to be reworked respectively.
- ADbasic include files :   ADwpEXT.inc (new instruction because CAN-LS : `GET_LINE_STATUS`
                                            ADwL16.inc   (for ADwin-L16-DIO1 and ADwin-L16-CO1)
- ADwin driver bugfixes :
    - improved errorhandling for diverse functions
    - improved USB driver (errorhandling)
- ADwin operating system (ADwin9.BTL) :
    - decrease in the influence of the process- timing, which could be caused by :
        - `BEGIN_CRITICAL_SECTION` (often used in : ADwin-Pro)
        - or division in a process with low priority
- Developer Software :
    - improvements in Visual Basic, Labview and C - driver

- ADPro Version 2.7 : new : identification/calibration of new module Pro-AIN-F-4/14, Pro-AIN-F-8/14
- L16Calib   V1.0   this is the calibration program for ADwin-Light16
- ADconfig V2.2 : (configuring of several Devices is more user friendly now)
- ADtools V4.4 :
    - new : TString (for displaying and editing of ADbasic- strings)
    - TPar_FPar : new : individual labelling of each Par / FPar-line
    - Bugfixes
- ADfind_dll V 1.0   searches for all ADwin- DLL and BTL files, which are stored on the PC

most important features of this version compared to version 3.20.0101 :

- ADwin driver feature :
    - higher data transfer rates with GetData_Long, ..._Float, ..._String, ..._Double on ENET, if firmware of the ADwin ENET interface >= 2.5 and if <= 1750 data are transferred from the ADwin- system
- ADwin driver bugfixes :
    - occasional problem (windows- protection fault) with GetData function on networks, which have a lot of traffic
    - occasional problem (wrong errorcode) with SetFifo function on ENET
- ADPro version 2.6 : new : identification of new counter module Pro-CO4
- ADbasic include files :   ADwpAD.inc   (because of new Pro-AIN-8/16-RB , Pro-AIN-32/16-RB ,
                                                                                        Pro-AIN-F-4/14, Pro-AIN-F-8/14)
                                           ADwpDIO.inc   (new: instructions for Pro-CO4 (and SSI))
- Developer Software :
    - Testpoint driver version 1.3.6 with the following new actions :
        - Get_Last_Error
        - Read Parameter All, Read Parameter Block
    - Labview driver version 2.0 with the following new functions:
        - errorhandling conformable with Labview (error wiring via Error In, Error Out : based on Get_Last_Error, Get_Last_Error_Text)
        - Get_Par_Block, Get_FPar_Block
        - GetData_String, SetData_String, String_Length
        - Process_Status, Data_Length, Set_Globaldelay, Get_Globaldelay, Set_Language
- ADEthFlash V1.5   (new : EEprom support)
- ScanAEI V1.2   (new : If DIL-switch 1 is present, the version number is displayed with an appended ".1")
- ADtools : bugfixes on Tgraph and TProcess
- ADconfig V2.1 :   easier user guidance for the configuration of Ethernet

most important features of this version compared to version 3.00.3011 :

- Window XP support (new USB driver)
- ADbasic version 3.20.01 : new :
    - Libraries   (see : ADbasic3.20-lib_eng.pdf)
    - String functions (see : ADbasic manual : ADbasic3_eng.pdf)
    - „Syntax Color"   (highlighting of ADbasic keywords, comments, etc.)
    - Autoindent
    - multiple "Undo" and "Redo"
    - "Open All Includes" (opens all files, which are included by the **#INCLUDE** command)
    - "Tabsize" now adjustable (Default Tabsize = 2 , therefore it may be necessary to check the format of those ADbasic programs, which are usingTABs)
    - On right mouseclick :
        - (Un-)Comment Block   (changing multiple codelines to comments and vice versa)
        - Indent/Outdent
        - Mark Controlblock   (on right mouseclick on a line, which contains **IF , ELSE** or **ENDIF,** the whole textblock of the **IF – ELSE – ENDIF** structure will be highlighted ; the same is also valid for :   **DO .. UNTIL, FOR .. NEXT**)
    - Info window   (shows several compiler- error messages and warnings)
    - diverse bugfixes (e.g. at **SELECTCASE**)
- ADPro version 2.4 : new : calibration function now has adjustable gain; binary input possible; ability to switch between UNI/BIP voltage ranges;   identification of new module AIN32/16RB
- ADtest V1.4 : last used Device No. is now saved
- ADconfig V2.0 :   diverse improvements, timeout now adjustable with resolution of 100 ms

- ADwin driver :
  - better error handling
  - bugfix at Set_Fifo (error occurred only with Ethernet, if Float Data were converted to Long DATA(s))
  - bugfix at process-scheduling of low priority processes
- Developer Software :   Visual Basic , Delphi and C – driver with the following new functions :
  - Get_Last_Error, Get_Last_Error_Text
  - Get_Par_All, Get_FPar_All
  - GetData_String, SetData_String, String_Length
  - Process_Status, Data_Length, Set_Globaldelay, Get_Globaldelay, Set_Language
  - etc.
- ADtools V4.1 (new : TFifo and TBin)
- ScanAEI V1.0   (scans all ADwin-Ethernet interfaces, which are located in the same TCP/IP- subnet
                                                                                            as the PC)
- Linux : latest driver and (for the first time) XADbasic_beta (= ADbasic-GUI)

most important features of this version compared to version 3.00.2735 :

- ADPro version 2.2 : new : calibration function for Rev. B modules
- ADtest V1.3 : now also GOLD and Light-16 is supported ; Info window shows all installed ADwin software packages
- ADconfig version 1.7 : now available : 4-digit Linkaddress
- ADbasic : diverse bugfixes on : DAC- instruction, libraries, external event, integer division
- diverse updates and bugfixes on : ethernet, profibus, ADserver.exe, standard processes,   Bootloader (Link), process-timing of low priority processes, communication problem on very big blocktransfer of data under WinNT and Win2000 fixed, problem on starting and stopping of processes under Testpoint fixed
- developer software :
  - Labview driver adapted for Labview 6.0
- for the first time on CD : ADbasic development system and drivers for Linux

most important features of version 3.00.2735 compared with version 3.00.2733 :

- ADEthFlash V1.2 (for programming the bootloader and updating the firmware of ADwin-systems with Ethernet interface)
- ADTools V 3.6
- Significant improvement of the transfer rate of ADwin-light-16

most important features of version 3.00.2733 compared with version 3.00.2332 :

- support of ADwin-systems with Ethernet interface
- under Win2000 also ADPCMCIA and PCI is now supported.
- under Win2000 the ISA-LINK cards are managed now in the "Device Manager".
- new ADbasic instruction : **SELECTCASE**
- "16 Bit resolution" is now the default setting in the ADbasic Compiler Options
- improvements in the accuracy of calculations with the power- function (^)
- improvements of the functionality and the (transfer rate) performance of USB